

ITEM Number	DESCRIPTION	FURNISHED BY		INSTALLED BY	
		O.G.&E.	CONSUMER	O.G.&E.	CONSUMER
1	Service Lateral	Х		X	
‡2	Service Lateral Raceway		Х		Х
** 3	Current Transformer Enclosure	Х			Х
+4	Transformer rated Meter Base	Х			Х
5	Service Equipment		Х		Х
6	Metering Conduit 1-inch		Х		Х
7	Meter	Х		Х	
*8	Grounding Electrode & Grounding Electrode Conductor		х		х

- ‡ Size and number of conduits as specified by OG&E
- + Alternate location is shown dotted
- \*\* Current transformer enclosure shall be bonded to neutral block
- \* Not shown

#### Notes:

- 1. Where metering equipment is exposed to vehicular traffic a protective pipe should be installed in concrete 4-ft in front of metering equipment.
- 2. Wiring from CTs to meter is not to exceed 20 feet in total length.
- 3. OG&E equipment is to be installed on outside surface of structure and is not to be recessed.
- 4. Refer to U16 for proper identification and marking.
- 5. Refer to U760 & U760.1 for metering requirements.
- 6. CT Cabinet is not to be used for equipment grounds or as a raceway.

# METER INSTALLATION FOR CURRENT TRANSFORMER METERING

SINGLE AND EXISTING 3 PHASE ONLY 800A MAXIMUM


SUPERSEDES AUG 2019 ISSUE

training, know-how, or ir APPROVED

Oklahoma Gas and Electric Company ©

U765.1

### UNDERGROUND STANDARD Version I - JUN 2021



#### NOTES:

- Current transformers to be installed in the position that provides the best spacing for line and load conductors.
- Service and metering connections made by OG&E.
- Verify that customer has established a driven ground at their main switch panels.
- Position supply cable to center of connector block.
- Place identifying tag on service conductors with information relating to where service is coming from (pedestal, transformer, pipe or no pipe under driveway.) Refer to U16.
- Wiring from CTs to CT meter is not to exceed 20 feet in total length.
- OG&E to bond CT cabinet to neutral block using #6AWG copper wire.
- Secure connection box #428962 with (3) Mac-It head bolts (3/8" x 1") #301404 upon energizing.
- Not to be used for equipment grounds or as a raceway.

## **TABLE 1**

to provide proper wire spacing

STOCK ACCOUNT	CABINET DIMENSIONS
428962	30 x 36 x 14


#### CONNECTOR BLOCKS TABLE 2

STOCK ACCOUNT	SECONDARY TAPS	SERVICE TAPS	MAX CURRENT
264358	2 6-AWG thru 350-KCMIL	2 6-AWG thru 350-KCMIL	600
264195	2 6-AWG thru 500-KCMIL	4 6-AWG thru 500-KCMIL	800
1019876	2 0-AWG thru 750-KCMIL	4 0-AWG thru 750-KCMIL	1200
264224	2 0-AWG thru 750-KCMIL	8 0-AWG thru 750-KCMIL	1200

**CONNECTION DIAGRAM** WITH OPTIONAL SELF-CONTAINED METER SINGLE OR EXISTING 3 PHASE ONLY 800A MAX SUPERSEDES FEB 2021 ISSUE

Signatures on File

APPROVED



#### NOTES:

- 1. Refer to U760 for Metering Guidelines.
- 2. Service and metering connections made by OG&E.
- 3. Verify that customer has established a driven ground at their main switch panels.
- 4. Place identifying tag on service conductors with information relating to where service is coming from (pedestal, transformer, pipe or no pipe under driveway.) Refer to U16.
- Wiring from CTs to CT meter is not to exceed 20 feet in total length.
- 6. OG&E to bond CT cabinet to neutral block using min. 1/0 AWG copper wire.
- 7. Secure connection box with series #1 padlock #301236 upon energizing.
- 8. Current Transformers to be installed by OG&E meter department.
- 9. Not to be used for equipment grounds or as a raceway.
- 10. Center of meters must be placed 48" to 60" above final grade.
- 11. To minimize Arc Flash Hazards, 480V Applications MUST NOT terminate conductors on the right face of the terminal spade.

CONNECTION DIAGRAM
1200 AMP, CT METER INSTALLATION
WITH OPTIONAL SELF-CONTAINED METER

APPROVED SUPERCEDES JUN 2021

ISSUE