## **OG&E Functional Demands Summary**

## JOB TITLE: Foreman Plant Maintenance and Supervisor of Plant Maintenance Physical Demand Level (PDC): Medium

Facility: OG&E

## PHYSICAL DEMANDS

The physical demands described here are representative of those that must be met by an employee to successfully perform the essential functions of this job. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions.

	Constant	Frequent	Occasional	Comments/Task Description
Crawling			X	In order to reach repair area
Stooping			Х	Up to 5 minutes
Crouching/ Kneeling			X	
Climbing			X	
Standing			X	
Walking			X	
Hand Coordination		Х		
Sitting		Х		
Reach			x	
overhead/forward			^	
Repetitive Motion			X	
Push/Pull			X	

This position requires an employee to lift/carry:

	Constant	Frequent	Occasional	Distance	Comments
1 – 35 lbs			30	Varies	
36 – 50 lbs			50	Varies	
51 - 75 lbs					
75 - 100 lbs					
Push			88		
Pull			88		

## WORK ENVIRONMENT

The work environment characteristics described here are representative of those an employee encounters while performing the essential functions of this job. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions.

	Constant	Frequent	Occasional	Comments/ Description
Hot/ Cold			X	
Wet			X	
Vibrations			X	When using power tools
Chemicals				
Confined space			X	
Variable floor surface		X		Concrete, asphalt, dirt, grass
Dust			X	
Heights			X	
Awkward Positions			X	

Frequency:O=Occasional (1-33%); F=Frequency (34-67%); C=Constant (67-100%)Repetition:Occasional 1-4 reps/hr; Frequency 5-24 reps/hr; Constant 25+ reps/hr